



2026

JIANGSU YUNYI ELECTRIC CO.,LTD

IGNITION COIL


T0001	T0125	T0125A
 1L8Z-12029-AB,1L2U-12029-AA,1L2Z-12029-AA,F7TZ-12029-AB,3W7E-12A366-AA,3W7Z-12029-AA,FD503,D G508,DG491	 SUZUKI 3705010-01	 33410-60G10,Excluding holder
T0126	T0126A	T0126B
 SUZUKI 3705010A2	 SUZUKI 3705010A4	 SUZUKI 3705010B2
T0127	T0127A	T0127B
 SUZUKI 3705010B3	 SUZUKI 3705010A8	
T0128	T0128A	T0128B
 SUZUKI,3705010-04,33400-66D10,3705102-B07-00A	 SUZUKI,33410-77E01,33410-65G00,33400-65G01,9C 19-0370,33400-65G00,UF280	 MITSUBISHI 4G18,MITSUBISHI MD361710,DENSO,099700-0480

T0128C	T0128D	T0128E
 MITSUBISHI 4G18	 JL475Q, CM8	 中华俊捷1.8
T0128F	T0128G	T0128H
 SUZUKI,33400-62J00-000	 3705010E, JL466Q1	 3705010-G03, 志阳DQG1122A
T0129	T0129A	T0131
 SUZUKI,3705010-03,JL472Q1,JL474Q1,SC7101,SC7130	 SUZUKI,3705010-03,JL472Q1,JL474Q1,SC7101,SC7130	 CHRYSLER,4751253,5234210,5234610,5252577,4797293,C506,DODGE 19017110,UF97
T0132	T0132A	T0133
 DALHATSU,19080-Z9121,19080-87703,100297-0860,DALHATSU-2001	 DALHATSU,90048-52056,90048-52096,900482091,DIAMOND F-076,F-614	 NISSAN,22448-CJ00A,NISSAN,22448-ED800,UF591,0221 604020

T0133A	T0133B	T0133C
 BOSCH F01R00A013	 407.3705,70.3705,0221 504 027,40904.3705000	 LR010687,UF618,UF637
T0133D	T0133E	T0133F
 BOSCH,F 01R 00A 035	 K914560188A,0 221 504 022	 0 221 504 030,RENAULT,82 00 699 627
T0133G	T0133H	T0133J
 BOSCH,F 01R 00A 039	 F 01R 00A 047	 F01R 00A 048
T0133K	T0133M	T0133N
 F 01R 00A 056,杆子F01R10A210	 F 01R 00A 061	 F 01R 00A 065,比亚迪G6,有模块

T0133Q	T0133R	T0133S
 F 01R 00A 068,杆子F01R10A267,宝骏730	 F 01R 00A 092,奇瑞 艾瑞泽5,凯翼 x5,斯威X3	 F 01R 00A 023
T0133T	T0133W	T0133Z
 F01R 00A 053	 F 01R 00A 113,10239858	 A 172 158 01 03
T0134	T0134A	T0134B
 BOSCH F01R00A003	 LX300-6A,T04E010DP,408004SN,650utv	 LDA-D06A,270920457-0001,菱电系列电喷摩托车点火
T0134D	T0134F	T0134G
 A 173 158 01 03,C2010018457A0,9092810	 LX250GS-3,...+250RR,270920588-0001	 BOSCH,F01R00A003,春风150,不带杆子,只有主体

T0135	T0135A	T0136
 90048-52130	 90048-52129,FK0169	 12568062,UF303
T0137	T0137A	T0138
 GM 12558948,GM12556450,UF192,392-881732,3861267	 LAND ROVER,6H2E-12029-AA,P680A,LR002427,4603135,UF590	 12558693,H6T55171ZC,UF271,3859078,392-889925
T0138-P	T0141	T0141A
 12558693,H6T55171ZC,UF271,3859078,392-889925, Spark energy increased by 7%	 TOYOTA,90919-02164,GM 94404545,94853695,ISUZU,8-94404-545-0,UF111	 TOYOTA,90919-02207
T0141B	T0141C	T0141D
 TOYOTA,90919-02197,90919-02208,E-546,19500-74050,DENSO,029 700 7050,029 700 7051,VW J9091902197,UF72	 TOYOTA,90919-02135	 90919-02163

T0142  mitsubishi,MD338169,FREECA,DN6440\703\71 DLK/FLK	T0142A  mitsubishi,MD309455,FA0004	T0143  DIAMOND,FTM-063GT,33410-85120,33410-85000,33 410A60D30,F-076,GC-5,MIC-2000
T0143A  90048-52175	T0143B  90048-52101,F-718	T0144  GASOLINE ENGINE
T0145  GASOLINE ENGINE	T0145A  GASOLINE ENGINE,J5700-3705060A,37.5D-05011-A01	T0145B  GASOLINE ENGINE
T0145C  GASOLINE ENGINE,MKA00-3705063B	T0145D  GASOLINE ENGINE,M2000-3705061,圆插	T0145E  GASOLINE ENGINE,方插,37.F2-05010-C01,37.9Z-05010-E01


T0145F	T0145G	T0145H
 GASOLINE ENGINE,VG10002080190	 GASOLINE ENGINE	 202V25919-6003,0E247 SUN9E01,RE533001
T0145Y	T0146	T0146A
 30-2853,1698-1235	 GASOLINE ENGINE,HYUNDAI,27301-85010	 TOYOTA,90919-02205
T0147	T0147A	T0148
 TOYOTA,90080-19012,UF155	 TOYOTA 90919-02215	 MAZDA,B6S7-18-100,10917121,MAZDA2000(F2)
T0148C	T0149	T0149A
 F2G8-18-10X,F2G9-18-10X,B6S7-18-100, B6S8-10-10XA	 TOYOTA,90919-02212,029700-7952,UF156	 TOYOTA,90919-02213,UF170

T0150	T0150A	T0150B
 MITSUBISHI,H3T011,F-581,H3T024,F-696	 H3T023,F-695	 MITSUBISHI,H3TO3471,DIAMOND,F-761,PROTON,IGC-098
T0151	T0152	T0153
	 MITSUBISHI,MD314583,DIAMOND,FTMC-021A1	 TOYOTA,90919-02214,UF-204
T0154	T0154A	T0154C
 H6T12272A,MD362915,(total 222mm)	 H6T12471A,MD362913,(total 193mm)	 NISSAN,22448-91F00,2244891F00,BOSCH,0 986 JG1 223,0986JG1223
T0155	T0156	T0156A
 MD346383	 33410-77E10,33410-77E11,UF169	 33410-77E20,33410-77E21,33410-77E22,UF237,UF547

T0157	T0157-P	T0157A
 12570616,H6T55271ZC,C1511,D510C,8125706160,UF413	 12570616,H6T55271ZC,C1511,D510C,8125706160,UF413,Spark energy increased by 20%	 12573190,UF414
T0157C	T0157D	T0157F
 12658183,UF-742,12699383	 GM 10457730,19005218,12563293,863500377,ISUZ U,8-10457-730-0,DENSO 6737101,UF262,C1251	 12221C11,H6T55371AC,UF743,12619161,12669351,AC2011 AB-5015A
T0157F-P	T0157G	T0158
 12221C11,H6T55371AC,UF743,12619161,12669351,Spark energy increased by 20%	 AB-5015B,AC-2021,不带模块	 BENZ A2729060060,UF535
T0158A	T0158B	T0158C
 DELPHI,GN10235,13T163,有接地片,(橡胶灰色)	 Benz A0001501980,DELPHI 19005267,UF-535,UF585,...	 DELPHI 19005272,MERCEDES BENZ,A1569064400,A1569054300,A1561500380,1569060300,A1561500080,A1569060400,A1569060500,UF-609

T0159	T0160	T0160A
 099700-0860,12578224,12629646,12638824,UF491,UF645	 NISSAN,22448-2Y005,NISSAN,22448-2Y006,UF332,UF363 H6T10271A,COEFIR A33š	 22448-4W011,22448-4W010,MCP-2850,UF-331
T0161	T0161A	T0162
 NISSAN 22448-2Y000 NISSAN 22448-2Y001,NISSAN 22448-2Y010,YB-A178,UF348,UF586,A33	 UF328,22448-4W001	 NISSAN,22448-31U06,MCP-1350,UF232,A32š
T0162A	T0163	T0163A
 NISSAN,22448-31U16,H6T10271A,H7Y00571A	 NISSAN,22448-31U01,UF263,A32	 NISSAN,22448-AA100,22448-5L300,HANSHIN,MCP-1440,BOSCH,0 986 JG1 217
T0163D	T0163E	T0163F
 22433-60U02,22448-02U11,22433-60U01,MCP-300	 22433-59S10,22433-59S11,22433-59S12,MCP-200	 22448-6P000,22448-3H000,UF282

T0163K	T0164	T0164A
 22448-30P00,MCP-400	 NISSAN,22433-0M200,22433-F4302,CM1T227	 CM1T-230A,22448-1W600
T0164B	T0165	T0165A
 CM1T-230B	 NISSAN,22433-10G10,NISSAN,22433-03G01,NISSAN,22433-03G11,NISSAN,22448-03G01	 8943389230,UF64
T0165B	T0166	T0167
 UF83,DG450 DG464 22433-0B000,22433-65E00,22448-56E12,22448-65E00,UF38,SD8602	 22448-65E00,96320818,96336522	 NISSAN,22448-2Y502
T0167A	T0169	T0169A
 NISSAN,22448-2Y700	 22448-1LA0A,5C1893,C1835,UF650	 22448-1LA0B,UF677,C1836

T0169B	T0169C	T0170
 22448-EZ31B,UF812	 22448-EZ31A,UF813	 GM D523,D532,D530,8131936,1875894,1985473,10497132 CONP 12029A,5-71,IDO-4002S,DGG-419
T0171	T0171A	T0172
 CM11-109,4909 C,HITACHI,HONDA,30520-PWA-003,UF373	 30520-RBJ-003,UF627,UF675	 CM11-108,8723 C,HITACHI,HONDA,30521-PWA-003,UF374
T0173	T0173A	T0173B
 CM11-110,5215 C,HITACHI,HONDA,30520-PWC-003,UF581	 CM11-116,8215,HITACHI,UF626,30520-RB0-003	 30521-RBJ-003,30521-RBJ-S01,UF628,UF676,CM11-118
T0174	T0174A	T0174B
 NISSAN,22448-6N015,22448-6N000,22448-95F0A,UF351	 NISSAN,22448-7S015,22448-AR215,UF510,UF568	 NISSAN,22448-8H300,22448-8H315,UF350

T0174C	T0174D	T0174E
 HANSHIN,AIC-1721A,19500-E0011	 HANSHIN,AIC-1023A,19500-E0053	 HANSHIN,AIC-4021B,898089 5960
T0174F	T0174G	T0175
 19500-E0130	 19500-E0140	 HANSHIN,AIC-3102G,5816,NISSAN,22448-8J115,NISSAN,22448-8J111,22448-8J11C,UF349,17210-23900
T0175A	T0175B	T0176
 NISSAN,22448-AL615,UF401	 AIC-3116,22448-FY500	 FORD,6M8G-12A366,MAZDA,L3G2-18-100A,UF540,DG516
T0176A	T0176B	T0176B-H
 FoMoCo,6E5Z-12029-AA,6E5G-12A366,029700-8391,L3H1-18-100,UF516	 ZJ20-18-100,5-099700-087,UF-655,杆子无环	 ZJ20-18-100,5-099700-087,UF-655,杆子有一环

T0176C	T0177	T0178
 LFB6-18-100,099700-0981	 MAZDA,N3H1-18-100,DQ-2180,UF501	 HANSHIN,AIC-2408A,22448-EA000,UF-509
T0178A	T0178A-P	T0178B
 HANSHIN,AIC-2408N,22448-JA00C,22448-JN10A,22448-ED000,22448-3RC0A,22448-EN200,UF549	 22448-1HC0A,17210-15900,22448-1HM0A	 ZJ01-18-100,杆子无环
T0178B-H	T0178C	T0178D
 ZJ01-18-100,杆子有一环	 22448-1KT0A,22433-9807R,22448-1KT1A,UF-708	 HANSHIN,AIC-2809B,22448-EY00A,IGC0078,UF-617
T0178E	T0178F	T0178G
 22448-1KC0A,UF-659	 22448-ZE00A,22448-ZE00C,UF551	 22448-JF00B,UF638


T0178K	T0178L	T0178P
 HANSHIN,AIC-2409A,22448-JA10C,22448-JA11C,UF-550	 HITACHI,HMLGT1066R,22433-4808R,无模块	 XIC-BB20P L,22448-1KC3B,22448-5CA0A,UF-819,2.0 主体性能和T0178Q不同,178C主体
T0178Q	T0178R	T0178S
 22448-5NA0A,UF-841,天籁2.0T,主体性能和T0178P不同	 22448-5NA3A,22448-5RF0A,178Q主体	 22448-6CA1A,UF861,两环杆子,178Q主体
T0178U	T0179	T0179A
 22448-5RL0A,UF860,与T0178C参数不同,178Q主体	 ELDOR-TR,77250003,PROTON,PW812018,A2C53283938,031 B 6 5111	 ELDOR-TR,77257002,PROTON,PW812712,A2C53393840,012 A 1 0917
T0180	T0180A	T0181
 22448-AX001	 22448-AX001,一个环	 CM11-102,6VE1,8971363250,8971765540,88921373,UF245,IGC0048

T0182	T0182B	T0182C
 MITSUBISHI,33400-65J00,UF562	 H6T11171,33410-93J00,2613	 H6T11172,33410-87L00,2711
T0182D	T0182E	T0182F
 6S5-82310-00,H6T11272,2717	 H6T11271,6P2-82310-00,6P2-82310-01	 1832A042,H6T11471,UF599
T0182G	T0182J	T0182K
 H6T11571,6CB-82310-00,橡胶杆长127mm	 H6T11273,6EX-82310-00	 H6T11173,33410-96L00
T0183	T0184	T0185
 FK0400,22433-AA630,UF664	 MITSUBISHI,H6T60271,SAAB,12787707,UF-526	 22433-2428R,77350001,H 8201 154 128,22448-00Q0F,0 986 221 079,A2819060000,3 PINS(3颗插针),长杆子,UF-808

T0185B	T0187	T0187-P
 22448-6CT0A,77950002,3 PINS(3颗插针),短杆子	 CM5E-12A366-CA,CM5E-12A366-BC,B1222000096,C M5Z-12029-A,DG546,UF670	 CM5E-12A366-CA,CM5E-12A366-BC,B1222000096,C M5Z-12029-A,DG546,UF670,Spark energy increased by 8%
T0187A	T0187A-P	T0187B
 DG-555,FT4Z-12029-A,FT4E-12A366-EA,UF-773	 DG-555,FT4Z-12029-A,FT4E-12A366-EA,UF-773,Spark energy increased by 8%	 FK0442,BYD487ZQA-3705100
T0187C	T0187C-P	T0187E
 HL3E-12A366-AB,HL3Z12029A,HL3Z12029D,E177310 2469,DG560,UF826	 HL3E-12A366-AB,HL3Z12029A,HL3Z12029D,E177310 2469,DG560,UF826,Spark energy increased by 8%	 31316353,31359814,9487442,0 221 604 024,0 221 604 025,AG9G-12A366-BB
T0188	T0188A	T0188B
 CM5G-12A366-CA,UF736	 DS7G-12A366-BB,UF735	 BM5G-12A366-DB,BM5Z-12029-B,UF674

T0188D	T0189	T0189A
 GN1G-12A366-AA	 31312514,AD6HF 6106,VE13-2810010-ACA,VE15-2810010-AAA,UF756	 DX23-12A366-AC,UF730
T0189B	T0189C	T0189D
 JE3E-12A366-AB,JR3Z-12029-A,UF835,DG-565	 JL3E-12A366-AA,JL3Z-12029-AA,UF825,DG-564	 JR3E-12029-AA,JR3Z-12029-B,DG-566,UF869
T0189E	T0189F	T0190
 DG-580,KR3E-12A366-BA,KR3Z-12029-B,UF899,中等长度杆子	 H4P3-12A366-BB,UF-862,LR091616,UF-854,杆子长114mm	 CM11-121,30520-5R0-003,30520-5R0-013,长杆+插头
T0190A	T0190B	T0190C
 CM11-122,30520-5Z1-003,30520-5Z1-013,UF833,杆+插头筋在下	 CM11-124A,30520-59B-013,UF781,长杆+插头筋在下	 CM11-123,30520-5Z2-003,30520-5Z2-013,短杆子+插头

T0190D	T0190F	T0190G
 CM11-125A,30520-58G-003,杆子带一环+插头筋在下	 CM11-127A,30520-ZVL-003,杆子带两环,插头筋在上	 UF732,30520-5K0-A01
T0191	T0192	T0193
 V.W.,330905115A,BOSCH,0221502007,0221502008, SANTANA 2000	 V.W.377905105D,BOSCH,9220081504,F000ZS0105	 V.W.6N0905104,867905105A,867905104A,8679053 52,867905104,357905104,BOSCH1227022030,1227 030030,0221601003,UF207,UF364
T0194	T0194A	T0194B
 19005265	 DAEWOO,96253555,19005265,19005236,93363483, SUZUKI,33410-84Z00,UF503	 19005270,DA462-1AD,LF479Q1-3705100A,31600017
T0194C	T0194D	T0195
 24538287.0	 28091937,94702536,CE20131	 DA468QL1

T0195B	T0195B1	T0196	T0196A
			
BOCSH,0221 503 465,A11-3705110EA		PEUGEOT 597045,CITRON 96035284	PEUGEOT 597047,CITRON 96041378,FIAT 9604137880,CITRON XM2.0L,PEUGEOT 605
T0196B	T0197	T0197A	
			
7700749450,7700858138,7702218697,770250545 9,9220081505	7582152,7663177,7698431,7746152	10489421 8104894210 CE20003 E208 D577 50007,52-1549,DR-49,344	
T0197B	T0197C	T0197E	
			
10477977,3862176,D575	E46 D503A 5C1029 C846 GN10048 1115468 10477208,1115315 1115317 12498334 8011153150 83501871,DR37,8983501871,817378	10477944,DR43	
T0197G	T0198	T0198A	
			
96165049,01115467	7701031135,12336238,U-504,3287677-3,CHRYSLER ,T1031135,DUCELLIER 520064,2526023,2526023A,Lucas DLB 204	90449739,1208003,03474233,3474233	

T0199	T0200	T0200-P
 MARELLIBae 507AK,60705701,060605738010,citroen 97531206,Ducellier 2526009,PEUGEOT 597042,Lucas DLB 206,2526009A	 56029129AF,A1290608662,UF504,AM-43429297	 56029129AF,A1290608662,UF504,AM-43429297,Spark energy increased by 8%
T0201	T0201A	T0201B
 AL3E12029AC,1601131066,UF-631,C1800	 AL3E12029BC,1404234892,UF-639,C1801	 T
T0201C	T0202	T0203
 UF865,DG570,HL3Z-12029-B	 12029AA,7053859,574 905 105B,AF5FU,F000ZS0102,54790510513	 90048-52109,一个单插片,一个双插片
T0203A	T0206	T0206E
 90048-52109,定制款,两个单插片	 22433AA460,22433AA480,22433AA540,22433AA541, 22433AA640,UF508	 22433-AA421,22433-AA420,22433-AA560,22433-AA561,22433-AON00,FK0140,FK0333,FK0055,UF-480

T0206F	T0206G	T0206H
 22433-AA441,22433-AA530,22433-AA531,22433-AA411,5C1281,GN10435,UF-287	 22433-AA610,22433-AA611,22433-AA612,UF682,UF666,1788537,NGK 4125,GN10666	 22433-AA600,UF665
T0206J	T0207	T0207A
 22433-AA602,GN10678,UF-738	 DEPHI,8-19005-240-0,8-19005-249-0,8-19005-140-0,UF-251,杆子长137.5mm	 8-19005-250-0,8-19005-250-1,UF-252,杆子长143mm
T0208	T0208A	T0209
 UF415,C1323,JAGUAR,XW93-12029-AB,099700-0260	 MB029700-8040,UF347	 TOYOTA,90080-19017,BOSCH,0221 504 020
T0210	T0210A	T0211
 UF640,5149199AA,灰插头,长橡胶头,(68.6mm)	 5149049AB,UF601,黑插头,短橡胶头,(57.3mm)	 FK0488,1832A083,Mitsubishi,Outlander Sport. 2.4L. From 08/17

T0211B	T0212	T0212A
 1832A080	 90919-A2013,90919-02280	 90919-T2010,90919-T2011
T0214	T0216	T0217
 22433-AA222	 TOYOTA,90919-02216,UF228	 TOYOTA,90919-02217
T0218	T0219	T0220
 TOYOTA,90919-02218	 TOYOTA,90919-02219	 90919-02220
T0220A	T0220B	T0221
 RENAULT,7700854306,7700863021,7700872265,VAL EO 245066	 RENAULT,7700854307,7700872692,MARELL 1607,BAK 801 BK	 TOYOTA,90919-02221

T0222	T0224	T0226
 TOYOTA,90919-02222(1-4)	 TOYOTA,90919-02224(1-4)(3-2)	 TOYOTA,90919-02226(4-1)
T0228	T0229	T0229A
 TOYOTA,90919-02228,UF229	 HARLEY DAVIDSON,DC3-1,1106013,32-8055,3.0 OHM	 HARLEY DAVIDSON,DC10-1,53-398,2102-0419,1106014,3160965A,5.0 OHM
T0229B	T0230	T0230A
 DC9-4,0.7 OHM	 HARLEY DAVIDSON,DC8-1,1106008,32-8086,2102-0420,5.0 OHM	 HARLEY DAVIDSON,DC1-1,1106006,32-7789,3.0 OHM
T0230B	T0230C	T0230D
 HARLEY DAVIDSON,DC2-1,1.5 OHM	 HARLEY DAVIDSON,DC4-1,2.2 OHM	 HARLEY DAVIDSON,DC9-1,2101-0326,0.7 OHM

T0231	T231A	T0231B
 HARLEY DAVIDSON,16053,31609-65A,DC7-1,1106011 ,2102-0215,32-7793,5.0 OHM	 HARLEY DAVIDSON,DC5-1,1.5 OHM	 HARLEY DAVIDSON,DC6-1,1106010,32-7792,3.0 OHM
T0231C	T0232	T0232B
 31609-80,4.0 OHM	 31655-99	 53-417,DC6-4,1212003
T0233	T0234	T0235
 2102-0226,1212007,53-434,DC6-5	 31656-07,140412	 31614-83A
T0236	T0236A	T0237
 31696-07A,28058097	 31743-01	 582508,4-5179,18-5179

T0237A  0583740,583740,18-5170	T0237B  S9620,18-5176	T0238  DC1-2/DC1-3/DC3-2 1212011 3欧姆 双头
T0238A  DCK7-4,DC11-2,1212012 0.5欧姆 双头	T0238B  DC3-3,DCK7-1,DCK7-3,1212010,2102-0004,133-6030 3欧姆 单头	T0238C  DCK2-2,DCK3-1,DCK3-2,1212013, 0.5欧姆 单头
T0239A  850277.0	T0239B  PN8232	T0239D  蓝色: P/N201-0091 黑色: P/N201-0121
T0239D-P  蓝色: P/N201-0091 黑色: P/N201-0121 Spark energy increased by 10%	T0241  339-859738T1 线长: 225mm	T0241A  65W-85570-01 线长: 175mm

T0241B	T0241C	T0241F
 3G2-06040,3G2-06050,线长: 455mm	 33410-94400,线长: 465mm	 6E7-85570-19,线长: 185mm
T0241G	T0241H	T0241J
 680-85570-00-00	 18-5180,339-825101T,392-825101T,线长: 175mm	 F6T532,33410-95L10,33410-95L11
T0241M	T0241N	T0241U
 6F5-85570-11	 33410-94400,33410-92L11,33410-92L10	 3G2-06040-2,东发M18E2
T0241X	T0241Y	T0241Z
 6B4-85570-00 雅马哈E9.9D、E15D	 3B2-06170-0,东发M9.8B	 66M-85570-00,雅马哈F15, F15A

T0243  339-832757A	T0244  6R3-85570-01-00	T0244B  63V-85570-00,雅马哈9.9F、15F
T0244C  61N-85570-00,雅马哈30H	T0244D  6A1-85570-00,雅马哈2C	T0244E  3F0-06153-0,东发M2.5A,M3.5A
T0244F  697-85570-00	T0245A  DR 101132,福爱系统,电阻0.57Ω	T0245B  3051A-LGL3,大阳摩托车
T0245C  DFAA01100033,福爱系统,电阻3.4Ω	T0245D  万强机车,电阻2.2Ω	T0245G  369-06050-2,东发M5B

T0246	T0246A	T0247
 166-0820,541-0522,螺杆直径不同	 166-0804,166-0772,146-0643,螺杆直径相同	 827509-A10,827509-A8,114-7509
T0249A	T0249C	T0252A
 55639006000,3000549,ELDOR 77380010,KTM 250 300 XC-W	 MIU13377,77380004,624034,380.4.025.1A, 77380008	 F06060032,270920144-0001,XT110
T0253	T0254	T0255
 F06060002	 6BX-85571-00,雅马哈F6	 6H3-85570-10,雅马哈E60H
T0255A	T0255B	T0256
 66T-85570-00,雅马哈E40X	 6E0-85570-00,雅马哈4AC、5CMH	 R81034,K76B0-3705061,143128,F222 燃气点火线圈


T0257	T0268A	T0268B
 R81034,K76B0-3705061,143128,F222,燃气点火线圈	 40176017A,22448-SE100,22448-5E100,旧款,杆子无	 新款,杆子有一换
T0269	T0269B	T0269C
 90919-02269,GN10741,DILFR7K9G,UF811	 12666339,099700-266,UF-830	 12652405,12627120,099700-182,12654078,UF680
T0270	T0270A	T0271
 90919-C2008,90919-02271	 90919-A2010,90919-02277,UF-849	 JT4E-12A366-AD,KT4E-12A366-AA,JT4Z-12029-A,UF-826
T0272	T0273	T0274
 68211953AA,UF839	 79011003,55496698	 31501120000,01658529

T0275	T0279	T0280
 576295,8888481265	 56028394AD	 NEC 000120,0040100501000
T0280A	T0280B	T0281
 NEC90012A,075 4342 0000	 NEC90013A	 DENSO,OK013-18-100,UF283
T0281A	T0282	T0283
 DENSO,OK247-18-100A,OK2A3-18-100A,HYUNDAI,273 01-26002,UF133,UF253	 DIAMOND,90048-52127,19500-87101	 19500-B0010
T0284	T0290	T0290A
 MD325592	 HYUNDAI,27300-39050,27301-39000	 27300-39800,UF-431

T0290B	T0291A	T0291B
 27300-39700	 FORD TIERRA,ZL01-18-100B,MAZDA,AAY1-18-100, ZZY1-18-100,UF408	 MAZDA,FFY1-18-100,FP85-18-100C,UF407
T0291C	T0292	T0292B
 MAZDA,ZM01-18-100,UF276	 MARELLI,060780002010,060708038010,FIAT 7672018,FIAT 7626232,46548037,46543562,60805420,60809492	 RENAULT,7700 107 269,SE028915.000B
T0293	T0294	T0294A
 D539,D540,1103608,1103744,1103746,1103646,11 03662,1103663,10497771,10472401	 DODGE 90,MD 158956,EAGLE 91-94,PLYMOUTH 91-94, MITISUBISHI90-94,HYUNDAI,27301-23700,UF419	 HYUNDAI,27301-02620,27301-02600
T0294B	T0294C	T0294D
 UF593,27301-23900	 27301-37150,UF-498	 27301-37118,UF-425,UF-360,27301-37120,UF-357

T0294E  27301-02700	T0294X  27310-37120,UF-428,铁芯位置右边	T0294Y  27310-37130,UF-429,铁芯位置中间
T0294Z  27310-37140,UF-436,铁芯位置左边	T0295  HYUNDAI,27301-26600,CUF424	T0295A  HYUNDAI 5WY2407A
T0295B  5WY2820A	T0295C  27301-23510,50038,UF-340	T0296  HYUNDAI,27301-22600,UF308
T0296A  HYUNDAI,96453420	T0297  MITSUBISHI 4G13	T0297A T297B1  BOSCH 0221500803

T0297B	T297B2	T0297C	T0297D
 BOSCH 0221500802,471Q-2L-3705800		 BOSCH,F01R00A012,F 01R 00A 012,短杆	 BOSCH,F01R00A009,F 01R 00A 009,长杆
T0297E	T0297F	T0297G	
 F 01R 00A 020	 F 01R 00A 011	 F 01R 00A 024	
T0298	T0298A	T0298B	
 HYUNDAI,27301-38020A1	 HYUNDAI,27301-38020,UF285	 MITSUBISHI,MD325052,CW723220,LANCER 1.8I	
T0299	T0299A	T0299B	
 MITSUBISHI,MD362907,MD325048,89057964,MITSUBISHI 4G64,UF295	 MITSUBISHI,MD362903	 MD363552,UF523,和T0299E杆子不同	

T0299E	T0300	T0301
 MD363552,UF523,和T0299B杆子不同	 LADA,1.3012.3705,406.3705	 LADA,1.3032.3705,405.3705
T0302	T0303	T0304
 LADA,1.3122.3705	 24100593,FK0424	 96291054,F 005 X03 219
T0305	T0306	T0309B
 55561133 90490573,9187436,AIRTEX 4C1007,STANDARD 12495,UF-420,CB14,10 pins	 12647553,12673523,FK0452,C992	 A1779060206,28602576
T0311	T0350	T0350A
 4010342,573101	 27300-2GGA0,UF-764	 27301-2B120,UF-817

T0350B	T0351	T0351A
 27301-03HA0,UF843	 27300-2E601,UF-816	 27301-2B140
T0351B	T0351D	T0351E
 27301-03AA0,UF857	 27310-3L000,UF844	 27310-3L030,UF863
T0352	T0355	T0355A
 JX6Z-12029-A,JX6Z-12029-B,DG574,JX6Z12029A	 27301-2M417,UF889	 27301-2M320,UF891
T0357A	T0358	T0372
 27300-2J300,5C2382	 27300-2JTD0	 CHERRY QQ0.8,S11-3705100,S11-3705110


T0372A	T0373	T0400
 21121-0724,372-3705110	 0K201-18-10XC	 BOSCH 0221506002,BENZ 000 158 7503,UF527
T0401	T0402	T0403
 BMW,1748017,1748018,12131748017,1213170382 5,NEC000040,NEC101000,12131703227,121390678 30,UF354,UF300无杆,与T0413通用。	 BENZ,000 158 7003,000 150 0280,BOSCH,0221 506 444	 BMW,121317 26177,121317 03359,121317 31884,121390 66468,UF226
T0404	T0404-P	T0405
 BENZ,000 158 7803,0221 503 035,UF359,2876049,4010425,Sea-Doo: 278001546,270600002,POLARIS:,4014295,4014296	 000 158 7803,0221 503 035,UF359,2876049,4010425,Sea-Doo: 278001546, 270600002,POLARIS:,4014295,4014296,Spark energy increased by 12%	 VOLVO,1275971,UF167
T0406	T0406A	T0407
 VOLVO 9125601,30713416,6M5G-12029-AA,0 221 604 001,UF341,黑色插头,杆子长度103mm。	 VOLVO,30713417,18677837,0221 604 010,1371607,UF517,灰色插头,杆子长度97mm	 VOLVO 1275602,UF365

T0408	T0408A	T0408B
 BENZ,A 000 150 1580,A 000 150 2980,UF555,BERU GERMANY,0 040 100 042,04T301 3	 CHANGAN,3705010-B02	 0 040 100 072,A 000 150 2580,UF658
T0408C	T0410	T0410A
 CHANGAN,3705010-B02-AA,3705010-B04	 22435-AA020,CM12-100C	 22433-AA370,22433-AA240,UF159
T0410B	T0411	T0411A
 22433-AA58A,22433-AA500,22433-AA50A,22433-AA580	 BOSCH,0221503026,OPEL,1208209,9118114,UF278	 BOSCH,0221503027,OPEL,1208210,9118115,UF279
T0412	T0412A	T0412B
 ZS 0009,A 000 150 17 80,BERU GERMANY,0 040 100 039,BOSCH,0 986 221 007,UF536	 PORSCHE,996 602 104 00,997 602 102 00,997 602 104 00,BERU 0040100036 ZS036,STANDARD UF-544	 PORSCHE,906 602 101 01,906 602 102 00,906 602 103 01,996 602 101 01,996 602 102 00,997 602 107 00,BOSCH,0 986 221 016,UF-346

T0412C  0 040 100 178,ZS178	T0412D  0 040 100 177,ZS177,997 602 107 02	T0413  0 221 504 004,与T0401可以通用
T0414  AUDI,058 905 105,BERU,0 040 100 013,UF290	T0415  BENZ,A 000 158 7203	T0415A  BENZ,A 000 158 7203,BOSCH,0 221 504 001,UF-795
T0415B  BENZ,A 000 158 7203,0221504001	T0418A  PC91,PC2041D,PCE382.1033	T0418B  E2FZ-12029-A,12321405 12336833 19017194 F-503,F-1953 DG-325A
T0418C  特种设备点火线圈,带接地线。参数同T0418A	T0418D  AB-3103C,AC2008	T0419  27301-23003,UF178

T0419A	T0419B	T0419C
 27301-22040,27301-22050,UF-176	 27301-33510,27301-33520,UF195	 27301-22037,UF206
T0419D	T0419G	T0420
 27301-26080,UF243	 27301-37100,27301-37105,UF284	 OK9BV-1810X
T0421C	T0422	T0423
 F 01R 00A 070,铃木雨燕1.3L	 0 221 504 025,504085566	 A 274 906 14 00,A 274 906 06 00,28165252,UF-734, UF-842,22448-HG00B,22448-HG00E,22448-2V70A,22448-HG00C,C1048
T0423A	T0423B	T0423C
 A 270 906 05 00,A 270 159 00 42,0 221 604 036,UF-744	 A 282 906 00 00,22433-2935R,22448-00Q0J,ZS0022-HMLGT1654R	 1339060600,28165252,UF778

T0423D	T0423E	T0423F
 A 264 906 12 00,UF887	 254 906 10 00,254 906 04 00	 254 906 11 00,254 906 05 00
T0424	T0424A	T0424B
 A2769060260,A2769063500,A2721500280,A2761500080,A2769060160,A2769060259,BOSCH 0221604034,0221604032,0221604026	 A 276 906 79 00,DELPHI,28301247,UF777	 A 276 906 45 00,A 276 906 51 00,276 906 06 01,0 221 604 040,0 221 604 041,0040 102 094,ZSE094,UF-806
T0424C	T0424D	T0424E
 A 276 906 37 00,0040 102 070,ZS0015,UF741	 1579060000,ICA64426,GN10756,UF-728,UF-733,UF-748	 276 906 52 00,UF-809
T0424F	T0424G	T0425
 A 256 906 02 00,181117,001744,ZS0023	 A 256 906 05 00,200515,114617,ZS0023	 OK30E-18-10X,UF-335

T0425A	T0426	T0428
 OK30A-18-10X	 MD158409,MD163599,MD179787,MD192126,MD310298,88921259,88921260,88921338,96067256,MD184230	 1535713,1671690,55200112,55208723 9S5112029AA
T0429	T0491	T0491A
 254 906 14 00	 ISUZU 8-01101-038-0,GM 1104038,1104047,10450424,10490192,10450424,OPEL 1208051,DAEWOO 96350585	 ISUZU 8-01101-038-0,GM 1104038,1104047,10450424,10490192,10450424,OPEL 1208051,DAEWOO 96350585,UF336,UF356
T0492	T0492B	T0492D
 V.W.,032905106,032905106B,UF277	 V.W. AUDI,06A 905 097,06A 905 104,BORA 2.0L,OCTAVIA 2.0L,GOLF 2.0L,NEW BEETLE 2.0L,SANTANA 3000,UF484	 7789346,46480361
T0493	T0494	T0494A
 V.W.,032905106,032905106 B,SEAT032 905 106B,SKODA032 905 106,032 905 106	 597048,597060,96074054,9607405480,2529040A	 GM 90458250,OPEL 1208071,SIEMENS 5WK0611,VALEO 245057,CD440 2526055 2526055A,597049

T0495	T0495A	T0495B
 DIAMOND,22433AA400,UF193	 22433-AA41A	 22433-AA430,FH0161
T0496	T0496A	T0497
 CHRYSLER,04557468,04671025,04609080,MO4557468,MO4777667,5269670,UF183,UF189,UF403	 插头长36mm,04609103AB	 FORD,E8TE-12029-AA,928F-12029-CA,19017116,1649067,F3U-12029-AA,YS4U-12029-AA,F5RZ-12029C,F5LU-12029 A,ZZMO-18-100,FSD7-18-100,FD487
T0498	T0498A	T0498B
 FORD,1075786,1119835,1130402,1S7G-12029-AB,1S7G-12029-AC,1S7G-12029-AD,988F-12029-AB,988F-12029-AC,MAZDA YF091810X ME85-02,YF09-18-10X,FD497,FD-501	 MAZDA,L813-18-100,MAZDA 6	 FORD 4M5G12029ZB,1459278,1350562,UF654
T0498C	T0498D	T0498E
 FoMoCo,988F-12029-AD,1S7G-12029-AC,YM2F-12029-AB,BOSCH 0221503490,988F-12029-BA	 CM5G-12029-FC	 F000ZS0235,F000ZS02435

T0499	T0500	T0600
 OPEL 1208063,Pontiac 1103929,D547 Pontiac 1994,1103872,10457075	 30510-PT2-006,UF89	 078905104,078905104A
T0601	T0601A	T0602
 V.W. 021 905 106C,V.W. 021 905 106B,UF338,C1320	 V.W. 021 905 106,UF163,150001810,95VW-12029-AA,003 158 50 01,021 905 106 A	 4443971.0
T0603	T0691	T0691A
 058 905 101 A,058 905 105 A,058 905 447 C,0 221 603 002,0 221 603 003,0 221 603 004,0 356 100 104	 6V87QE-3705010B,GASOLINE ENGINE	 6V87QE-3705010B,GASOLINE ENGINE
T0692	T0693	T0694
 MOR1F2E 12029AC,CD 0425 E01 DM,FORD,919F-12029-AA,19017114,6630365,FORD 89-99,1F2U-12029-AC,1F2Z-12029-AC,FD498	 GASOLINE ENGINE	 560298AA 5603250 88921268,DODGE 53006565 56032520AB,DODGE 94-96,UF305

T0695	T0696	T0697
 6383157,E9DF-12029-AA,E9DZ-12029-A,F0TZ-12029-A,F1DZ-12029-A,F3DU-12029-AA,F3DZ-12029-A,F57U-12029-AA,F57Z-12029-A,F82U-12029-AA	 DENSO 0297006760 0297007180, JAE-456, FORD 89-99 MERCURY 95-99 6630365, 6958305, 919F-1202 9-AA, E9SF-12029-AA, 19017114, F5SZ-12029-A, UF488	 BOSCH0221503010, OPEL1208007, OPEL90492255, 90 511450
T0697A	T0698	T0699
 OPEL1208075, OPEL90563160, HOLDEN90541062, 101 2080075, UF379	 H6T40171ZC, 12595088, UF434	 FORD, EF-12029-A, 9220061800
T1101	T1101A	T1102
 TOYOTA, 90080-19016, 90919-02234, UF267	 TOYOTA, 90919-02234, UF267	 TOYOTA, 90919-02240, 90919-T2003, 90919-02265, 90 919-02229, 90919-02270, UF316
T1103	T1104	T1104A
 TOYOTA, 90919-02230, 90919-02259, 90919-02249, 90 080-19027, UF230, UF493	 TOYOTA, 90919-02239, 90919-02262, 90919-T2002, Toyota Aviaon 08/199-12-2004, 90080-19019, 90080-19015, UF247	 TOYOTA, 90919-02236

T1104B	T1105	T1105-P
 90919-02235	 4M5G-12A366-BC,1224925,1314271,FD505,DG507	 4M5G-12A366-BC,1224925,1314271,FD505,DG507,Spark energy increased by 14%
T1105A	T1105A-P	T1105B
 1L2U-12029-AA,1L2Z-12029-AA,F7TZ-12029-AB,3W7E-12A366-AA,3W7Z-12029-AA,F7TU-12A366-CB,FD503,DG508,DG491	 1L2U-12029-AA,1L2Z-12029-AA,F7TZ-12029-AB,3W7E-12A366-AA,3W7Z-12029-AA,F7TU-12A366-CB,FD503,DG508 DG491,Spark energy increased by 14%	 2W4Z-12029-AC,XW4U-12A366-AC
T1105C	T1105C-P	T1105D
 2W4Z-12029-BD,FD506,DG515	 2W4Z-12029-BD,FD506,DG515,Spark energy increased by 14%	 MOTORCRAFT DG528 HOLLANDER,610-00152 610-58562,JAGUAR 1W4Z12029AA,1W4Z12029BA,2W4A12029AB,2W4Z12029AC,C2S42751,WELLS C1346,SMP FD496,DG517
T1105E	T1105F	T1105F-P
 FORD,BA-12A366-A,3R2U-12A366-AA	 FORD 1R8E-12A366-AC,18LZ-12029-AA,18LZ-12029-AB,1L8Z-12029-AA,1L8Z-12029-AB,FD502,DG500,MAZDA,AJ51-18-100A,AJ09-18-100,1L8Z-12029-AB,9L8E-12A366-AA	 FORD 1R8E-12A366-AC,18LZ-12029-AA,18LZ-12029-AB,1L8Z-12029-AA,1L8Z-12029-AB,FD502,DG500,AJ51-18-100A,AJ09-18-100,1L8Z-12029-AB,9L8E-12A366-A,Spark energy increased by 14%

T1105G	T1105H	T1105H-P
 1F3Z-12029-AA,4L7Z-12029-AA,DG512,DG543,UF191	 3L3E-12A366-CA,3L3Z-12029-BA,DG511,FD508	 3L3E-12A366-CA,3L3Z-12029-BA,DG511,FD508,Spark energy increased by 14%
T1105K	T1105L	T1105L-P
 FORD 88921347,F6DU-12A366-AB,F6DU12A366AB,F6DU-12A366-AA,F6DU12A366AA,F6DU-12A366-AC,F6DU12A366AC,F6DZ-12029-A,F6DZ12029A,F6DZ-12029-A A,F6DZ12029AA,F6DZ-12029-EA,F6DZ12029EA,MOTOR CRAFT...	 8L3Z-12029-A,8L3E-12A366-AA,DG-521	 8L3Z-12029-A,8L3E-12A366-AA,DG-521,Spark energy increased by 14%
T1105M	T1105M-P	T1105N
 9E5Z-12029-A,9E5E-12A366-AA,9E5G-12A366-AD,DG522	 9E5Z-12029-A,9E5E-12A366-AA,9E5G-12A366-AD,DG522,Spark energy increased by 14%	 EE03A,4G4E-12A366-AA
T1105Q	T1106	T1106A
 4015072,4011834	 AUDI,06B905115H,06B905115R,06B905115L,06A905115,1.8T,BOSCH,0 986 221 024,UF411	 022 905 100A,022 905 100D

T1106B	T1106C	T1106D
 06B 905 115E,06B 905 115B,1.8,UF274	 06C 905 115L,06C 905 115E,06C 905 115H,06C 905 115M	 07K 905 715F
T1106D-P	T1106E	T1106E-P
 07K 905 715F,Spark energy increased by 8%	 06E 905 115D,06E 905 115A,06E 905 115B,06E 905 115C,06E 905 115E	 06E 905 115D,06E 905 115A,06E 905 115B,06E 905 115C,06E 905 115E,Spark energy increased by 8%
T1106F	T1106G	T1106J
 022 905 100,022 905 100 C,022 905 100 F	 0 221 604 115,UF575,729 54031 101	 077 905 115Q,077 905 115C,077 905 115E,077 905 115F,077 905 115H,077 905 115T,UF418
T1107	T1107A	T1107B
 HYUNDAI,27301-23400,BAE400D,0119-6-21278	 HYUNDAI,27301-26640,HYUNDAI VVT,UF499	 HYUNDAI,27301-26640,HYUNDAI VVT,GASOLINE ENGINE

T1107C	T1107D	T1108
 HYUNDAI,27301-26640	 27301-37410	 BD0074445A,ELDOR78300001,CHERRY QQ0.8,S11-3705110EA
T1109	T1109A	T1110
 POLO,036 905 100A,036 905 100B,036 905 100C,036 905 100D,036 905 100E,BOSCH,0986 221 023	 POLO,BB,036 905 715A,036 905 715F,BOSCH,0 986 221 023	 BOSCH 0221504461,LADA,2112-3705010-10,350023 250,050203050,1220703202,与T1110A性能参数不同
T1110A	T1110C	T1110D
 2112-3705010-10,45 7371 5278,64.3705 000,与T1110性能参数不同	 LADA,2112-3705010-10,2112-3705010-SL,2112-370 5010-12	 VAZ 2110-2112,大拉达,2112-3705010-13
T1111	T1112	T1112A
 TOYOTA,90919-02244,90919-02243,90919-02266,90 080-19023,UF333,UF494	 RENAULT,7700875000,7700107177,7700113357,77 00113357A,0040100052,8200208611,8200154186, SAGEM21595273-2,RENAULT2526180A,NISSAN22448 -00QAE	 RENAULT,22448-00QAB

T1112B	T1112C	T1113
 RENAULT:,2526180A	 8200 7658 82,7700 875 000,ELDOR 78419001	 HONDA,099700-070,30520-PMA-007,30520-PNA-007,30520-RAA-007,UF311
T1113A	T1113B	T1113C
 HONDA 099700-115R	 099700-148/147/149,30520-R40-007,UF602	 TC-28A,30520-PNC-004,UF-417,30520-RWC-A01
T1113D	T1114	T1115
 TC-30A,30520-RL5-A01,UF-629	 TOYOTA,90080-19027,30520-T1103	 TOYOTA,90919-02246,90080-19025,UF506
T1116	T1116A	T1117
 33400-76G1,有模块	 33400-75F10,90048-86080,3705010-H01,无模块	 TOYOTA,90919-02237,UF323

T1118	T1119	T1119A
 TOYOTA,90919-02238,UF314	 TOYOTA,90919-02250,90919-02256,90919-A2005,90919-A2003,UF507	 TOYOTA,90919-02257,UF663
T1120	T1121	T1121A
 TOYOTA,90919-02248,90919-T2001,90919-T2005,90919-T2008,90919-A2001,90919-02260,90919-02247,UF495	 HONDA,099700-072,30520-PGK-A01,30520-PVF-A01,UF400	 30520-P8E-A01,30520-RCA-A02,UF242
T1121B	T1121C	T1121D
 30520-5A2-A01,099700-212,AN099700-212,CR1 2.4L,9代雅阁	 30520-5G0-A01,099700-213,AN099700-213,CR4 3.0L,9代雅阁	 CM11-207A,30520-ZY3-003
T1121E	T1121F	T1122
 30520-R70-A01	 U15H01	 099700-02510,90048-52126,099700-0570,19070-BZ 010

T1122B	T1122E	T1123
 90048-52125	 19070-97207	 HONDA,099700-101,099700-102,30520-RNA-A01,UF582
T1123A	T1124	T1125
 30520-RN0-A01,099700-149,UF624	 NISSAN,22448-4M500,CM11-205,ZSE021,UF326	 TOYOTA,90919-A2002,90919-02251,UF487
T1126	T1126A	T1126B
 19005277,37072001,3705100K7,28077401,2036004800,1016050462,19220270	 28244734,3705100E0100,3705100E2200,2036001200,4A153705020,SCA3705100	 96414260,25181813,28063913,1026090GG010,37050100A01000,37050100C01000
T1126C	T1127	T1127A
 28264038.0	 BMW 121317 12219,UF515,UF522	 BMW,0221 504 470,V 759493780-01,UF571,UF592

T1127B	T1127C	T1127D
 BMW,0221 504 471,7594935-02,灰胶套	 597091,0221504800,12137575010,0221504470,UF 598	 28114820,7 594 596-03,12138616153,UF-667
T1127F	T1128	T1128A
 12137619385,12138643360,12138647463,121386 78438,BMW,8615991 02,ELDOR,77460004	 mitsubishi 1832A025	 MITSUBISHI,1832A016,UF589,FK0320
T1128B	T1128C	T1128D
 MITSUBISHI,04606869AB,A05X2501784,UF502	 MITSUBISHI,1832A026	 KF0343,MN195805,1607576780
T1128E	T1128F	T1128G
 1832A031,UF643	 1832A028,FK0319,132 158 00 03,A 132 158 00 03,UF681	 04606824AB,04606824AC,B0582400221,UF557,IC63 7,5C1644

T1129	T1129A	T1130
 MR994643,UF532,6Y20-2337,FK0278,SMW250746	 MITSUBISHI,ME250963	 19070-B1020
T1131	T1131A	T1131B
 30520-PXH-004,TC-27A	 099700-0350	 TC-29A,30520-RS8-004
T1132	T1133	T1134
 JK099700-0990,19070-BZ040	 TOYOTA,90919-C2003,90919-02252,90919-02258,90919-C2005,UF596,UF619	 GM 9023781,DIAMOND,FK0374,A0991600089,BDW-IC-049
T1134A	T1135	T1135A
 96983945,UF725,C1846	 F6T558,2C0-82310-00-00,5PW-82310-00	 Yamaha(ÃÃÃ™,6B6-82310-00-00,6D3-82310-01-00,6D3-82310-00-00,8FP-82310-00-00,FAT1100,044-199

T1135B  F6T570,21171-1282,21171-0021,川崎	T1135C  F6T560,21171-0005,21171-0029	T1135D  F6T568,4C8-82310-00-00
T1135E  5EB-82310-00-00,F6T549,和T1135E单独参数	T1135F  F6T571A,1KB-82310-00-00,14B-82310-00-00	T1135G  F6T577,2HC-82310-00
T1135H  F6T553	T1135J  F6T574,8ES-82310-00-00	T1135K  129700-5330,33410-47H00
T1135L  F6T548,33410-87J01,5031469	T1135M  H-4092G,和T1135E单独参数	T1135N  129700-5230,33410-38H00,J0523

T1135P	T1135Q	T1135R
 129700-5350,21171-0028	 129700-4420,33410-24F10	 F6T56772,23P-82310-00-00
T1135S	T1135U	T1135X
 129700-4740,5TA-82310-10-00	 129700-5140,33410-37H00,J0514	 129700-4510,30700-MEE-641
T1135Y	T1135Z	T1136
 129700-4400,33410-35F11	 296000307,420664020,290664020	 PORSCHE,0 040 102 002,948 602 104 05,948 602 104 03,948 602 104 00,948 602 104 03
T1136A	T1136B	T1137
 948 602 104 02,948 602 104 04,948 602 104 06,948 602 104 10,948 602 104 11,948 602 104 12,948 602 104 13	 PORSCHE,9A1 602 104 00,9A1 602 104 01,9A1 602 104 02,9A1 602 104 03,9A1 602 104 04,9A1 602 104 05,9A1 602 104 06,BERU,0 040 102 052,0 040 102 005	 3603040-28K

T1137A  9004A-19001,JK099700-2080	T1137B  90919-02263	T1138  56028138AE
T1138A  56028138AD,56028138AB,56028138AF,UF270,UF399	T1139  HYUNDAI,27301-2B010,圆头	T1139A  HYUNDAI,27301-2B010,方头
T1140  BOSCH,0221 604 104,D501C,GM 12629037,0221 604 112,UF375	T1141  SUZUKI,33400-76G21,099700-095,与T1141D不同，橡胶头大孔径。	T1141A  6R83-12A366-AA,099700-1120,UF519,UF533
T1141B  33400-78M00,33400-62L00,099700-160	T1141D  33400-64P00,与T1141D不同，橡胶头小孔径。	T1142  HYUNDAI,27301-3F100,UF611

T1142A	T1142B	T1143
 HYUNDAI,27301-3F100,UF611	 27300-2G700	 HYUNDAI,27301-3E400,UF558
T1144	T1144A	T1145
 HYUNDAI,27301-3C000,UF546	 27301-3C100	 GM12632479,GM 12566589,DENSO,AN099700-1550, D508C,099700-1510,12590990,12610626,UF569
T1146	T1146A	T1147
 19500-B2040,19500-B1010	 19500-B2030	 ±øù, (±—57.5mm™, 19005266, UF481
T1147A	T1147B	T1148
 BOOT 65.5mm,19005287	 8M0039809,OK15 131708,DELPHI 19005251	 27301-2B000

T1149	T1150	T1150A
 6R83-12A366-BA,1X43-12029-AB,UF435	 04C 905 110 D,04E 905 110D	 VW AG,06L 905 110 C,06L 905 199
T1150C	T1150D	T1150E
 VW AG,04C 905 110 F,BorgWarner,0 040 102 700,短杆子	 VW AG,06K 905 110 J,06K 905 110 K,06J 905 110 C,06J 905 110 F,06J 905 110 G,BorgWarner,0 040 102 701,0 040 102 009,0 040 102 069,长杆子 UF-716	 946 602 104 00,ELDOR 775530002,UF760
T1150F	T1150G	T1150H
 06H 905 110 F,06H 905 110 G,ELDOR,77320008	 04C 905 110 G,28500570,短杆	 05E 905 110 C,77640004,UF936
T1150J	T1150L	T1150M
 030 905 110 A,030 905 110 B,030 905 110 C,030 905 110 D,0 986 221 074	 37050100-D01	 06K 905 110 N,28500571,长杆

T1150N	T1150W	T1150S
 288233,77430002	 06H 905 110 D,06H 905 110 E,06K 905 110 C,06K 905 110 G,长杆子	 28610332.0
T1150U	T1151	T1152
 28454712.0	 PE0118100,P51B18100,UF805	 099700-181,30520-R1A-A01,UF672
T1152A	T1153	T1154
 30520-55A-0050,FK0445	 02190938,50152	 33400-85K10
T1154A	T1154B	T1154D
 33400-51K40,33400-51K60,长橡胶头	 33400-85K20,33400-51K20,UF-634	 420666140,420666141,420666142

T1154E	T1154F	T1154G
 420666147.0	 420666145.0	 420666148.0
T1158	T1159	T1160
 19070-97206	 TOYOTA,90919-A2004,90919-A2007,90919-02255	 19070-BZ030,JK099700-2290
T1161	T1161A	T1161B
 90919-C2007,与T1161B相比,低压插头要长些	 90919-A2008,90919-02273,UF-796,9004A-19002	 90919-C2001,90919-C2004,与T1161相比, 低压插头要短
T1161C	T1161D	T1162
 90919-C2002,90919-C2006	 90919-C2007,方头---无反馈	 099700-0940,099700-2710,12594176,12670154,UF564,UF-543,与T1162B性能参数不同

T1162A	T1162B	T1163
 12585765,89017778,12585765,12602862,1267015 5,5C1552	 12597745,42597745,D598A,6737301,5C1616,UF543 与T1162性能参数不同	 4610,19500-B2050
T1164C	T1164E	T1165
 UF755,68200296AA,55250468,0 040 100 099	 68081914AA,68081914AB,68081914AC,0 040 100 089,UF673	 28198992,28159579
T1165A	T1165C	T1165D
 DF380(电喷)	 1702091,SFAA01050110,FPIA005	 GTB,100012
T1165F	T1165H	T1165J
 WXLDEFI-001,AT210514001	 线长120mm,钱江闪300,前部短线	 线长240mm,钱江闪300,后部长线

T1165N	T1165P	T1165S
 德尔福圆插,轻骑/大韩/晓星/300,前部短线	 德尔福圆插,轻骑/大韩/晓星/300,后部长线	 28198992,专用线长320MM
T1165W	T1165X	T1166
 德尔福方插,带铃木电喷帽,专用线长320MM	 德尔福圆插,直火花帽,奔达金吉拉300 轻骑大韩GV300S	 FKO435,UF-754, 0221504037,68242286AA, 68242286AB,杆子长170mm
T1166A	T1167	T1168
 55000827AB,A15110019015149168AH, 5149168AI, 5149168AJ, 7B0905715C, 7B0905715FUF648 杆子长133mm	 F 01R B0A 101,24106659	 BOSCH,F 01R 00A 071,3705010-A02
T1168A	T1168B	T1168E
 BOSCH,F 01R 00A 034	 BOSCH,F 01R 00A 052	 BOCSH,F 01R 00A 128

T1168F	T1168G	T1168H
 BOSCH,F 01R 00A 075	 BOSCH,F 01R 00A 042	 BOSCH,F 01R 00A 059
T1169	T1169A	T1169B
 BMW 7 715 847-02,UF-757	 7 715 858-01,102289-10 CN,12189R,R (右侧)	 7 710 874-01,102289-10,12137710874
T1169C	T1169D	T1169E
 7 715 846-02,102289-10 CN,Pulse 12199,12137715846	 7 715 848-01,12137715848	 7 722 679-02,12137722679,有模块
T1169F	T1169G	T1169H
 7 715 853-01,7 671 896-03,7 671 896-01,102289-10,11949	 8 523 972-01,8 523 972-02,8534177,78530001,有模块	 7 722 679-04,8534177,102289-10 CN,Pulse 12217,有模块

T1169K	T1169L	T1169M
 12137729707,12138569194,8 569 194-01,8525438,78441001,7729707,UF757	 7715856-02,8525438,7715856-01,102289-10 CN,Pulse 12193R,R (右侧)	 8 526 677-03,8 526 677-02,8534177,ELDOR,784430 02,12138526677,有模块
T1170	T1172	T1172-P
 22433-AA620,22433-AA621,UF668,FK0376	 BL3E-12A375 C10Z2002269,UF646,DG-549	 BL3E-12A375 C10Z2002269,UF646,DG-549,Spark energy increased by 14%
T1172A	T1172A-P	T1172B
 BR3Z-12029-A,6E5E-12A375-BE B1091206550,UF622,DG542	 BR3Z-12029-A,6E5E-12A375-BE B1091206550,UF622,DG542,Spark energy increased by 14%	 7T4E-12A375-EE,7T4Z-12029-E,UF553,DG520
T1172B-P	T1172C	T1172C-P
 7T4E-12A375-EE,7T4Z-12029-E,UF553,DG520,Spark energy increased by 14%	 AA5Z-12029-A,UF612,DG524	 AA5Z-12029-A,UF612,DG524,Spark energy increased by 14%

T1172D	T1172D-P	T1172E
 FR3E-12A375-AA,D1682200161,FR3Z-12029-A,UF824,DG561	 FR3E-12A375-AA,D1682200161,FR3Z-12029-A,UF824,DG561,Spark energy increased by 14%	 UF486
T1172F	T1172F-P	T1172G
 GR3E-12A375-AA,GR3Z-12029-A,GR3Z-12029-B,GR3Z-12029-C,D1692702111,DG558,UF780	 GR3E-12A375-AA,GR3Z-12029-A,GR3Z-12029-B,GR3Z-12029-C,D1692702111,DG558,UF780,Spark energy increased by 14%	 7T4E-12A375-GA,7T4Z-12029-F,DG563,UF823
T1172G-P	T1172J	T1173B
 7T4E-12A375-GA,7T4Z-12029-F,DG563,UF823,Spark energy increased by 14%	 UF881,LX6Z-12029-B,LX6E-12A375-AA,LX6E-12A375-B A,DG582	 A1351500280,A1351500180,MN195616,1351500180,1351500280,MN195452
T1174A	T1174B	T1174C
 FIAT 46777286,BOSCH 0 986 221 042	 FIAT 46777288,BOSCH 0 986 221 043	 60740304.0

T1175	T1176	T1176-P
 FIAT:,46473849,0046473849,Bremi:20187,CM11-202	 05149168AI,05149168AJ,19224B0,BOSCH,0 221 504 032,UF648	 05149168AI,05149168AJ,19224B0,BOSCH,0 221 504 032,UF648,Spark energy increased by 8%
T1176A	T1176B	T1176B-P
 68223569AD,68223569AB,68223569AC,UF-807,GN1 0951,19224B0,0221504 038	 UF751,68242286AA,长杆子	 UF751,68242286AA,长杆子,Spark energy increased by 8%
T1177	T1177A	T1177B
 BOSCH,F 01R 00A 058	 F 01R 00A 084,23871596	 F 01R 00A 081,24105479
T1177D	T1178	T1178A
 BOSCH,F 01R 00A 164,23595766	 KIA,27300-2E000	 27300-03150

T1179	T1181	T1181A
 KIA,27301-2B100	 Cummins,5310990,5626388	 Cummins,4330270,杆子 : 2899547
T1181C	T1181D	T1181E
 Cummins,3964547,3928263,3930027,3608003,3934684,5310989	 Cummins,5411556,杆子 : 4389407	 Cummins,4390412
T1181F	T1182B	T1183
 Cummins,5634407	 VOLVO,8687939,DENSO,099700-0890,UF574	 04609095AF,UF199
T1183A	T1183B	T1184
 04609088AC	 NGK #48724,SKU #U5230,5037127AB,UF642	 DE FK0443,1832A057,UF-815

T1184A	T1184B	T1184D
 DE FK0443,1832A059,5217E2	 DE FK0463,22433-AA70A,22433-AA70B,22433-AA700,22433-AA730,SU003-05259,UF-747,UF-767,UF-769,UF-774,UF-775	 DE FK0443,1832A062,UF-814
T1184E	T1184F	T1184G
 FK0443,3340084M000,33400-86PC0,33400-60R00	 22433-AA650,22433-AA651,22433-AA652,22433-AA67A,22433-AA67B,22433-AA680,22433-AA681,22433-AA690,22433-AA691,UF-710,UF-720,UF-721,UF-722,UF-723,UF-724,UF-737	 1832A067
T1185	T1185A	T1186
 17210-12900	 17210-14900	 6807 0492AD,UF649
T1187	T1188	T1188A
 12596547,ISUZU,8-12596-547-0,UF497	 KRK TT66,FK0444,无模块,473QE	 KRK TT19B,FK0398,有模块,473QB,黑色插头,与T1188B可以通用

T1188B	T1189	T1190
 FK0398,10915,IB5,3705100,有模块,473QB,咖啡色插头,与T1188A可以通用	 27301-3E100,UF554	 27301-04000
T1191	T1192	T1192A
 KRK TT14	 12635672,12670053,5C2095,C2036,UF802,H6T1547 1ZY,HNA-112-11,CB27 MEAA	 OPEL 1208109,55578392,GM 55569253,MITSUBISHI H6T15371ZC,STANDARD 12156,5569253DA,HNA-104-21
T1193	T1194	T1195
 TOYOTA,90919-02245	 44430036,4443006,6033236,UF384,5C1176	 099700-1070,6G9N-12A366,30684245,LR002954,UF 594
T1196	T1196A	T1199
 099700-0710,2W93-12A366-AB	 099700-0711,2W93-12A366-BA	 27301-03200

T1200	T1201	T1201A
 PEUGEOT 307,PEUGEOT 597080,PEUGEOT 597056,2526182A,CITROEN96363378	 PEUGEOT 206,PEUGEOT 597074,CITROEN,962815858 0,CITROEN96246755,96281585	 PEUGEOT 206,PEUGEOT 597079,PEUGEOT 5963.19,CITROEN96358649,CITROEN,000597079
T1201B	T1202	T1202A
 9654814480,26951960-3	 PEUGEOT,597087,9656695780,5970.A0	 9674680380,9800251580,V29010292
T1203	T1204	T1205
 PEUGEOT,5970.51,5970.A7	 9119567,1208008,90536194	 PEUGEOT 597075
T1206	T1206A	T1206B
 DELPHI 28125877,PHCC 55570160	 DELPHI 28163171,PHCC 55571790	 1104082,1208021,UF606

T1206C	T1207	T1207A
 GN10234,1208086,55561655	 UF296,56041476AA	 UF293,56041019
T1208	T1208A	T1208B
 275 150 0680,0001501080,0001502080,27515004 80,UF-578,UF-579,单只线圈	 A 275 150 05 80,A 275 150 07 80,257 150 05 80,000 150 11 80,UF-578,左排	 A 275 150 04 80,A 275 150 06 80,257 150 04 80,000 150 10 80,UF-579,右排
T1209	T1209A	T1209B
 96415010,BK 4391	 5WY2847A,TU5	 OPEL,1208307,19005212,47905104,BOSCH,0 986 221 039,FORD,W708593S430
T1210	T1211	T1212
 3705010A6	 KIA,0K011-18-100,UF306	 摩托罗拉01R4304R01, 摩托罗拉电喷系统, 五菱之光, 北汽福田等, MARSHALL:ME85-01,

T1213	T1214	T1215
 p/n 01R43059X01,S11-3705110JA	 LADA,2112-3705010-07,211-3705010-02,211-3705011-02	 ALFAROME0,76487970,CITROEN 597053,HONDA,3052 0-PDF-E00,ROVER ERR6045,LAND ROVER,ERR6566,60 586072,V.W.0489051051,FERRARI 134386,RENAULT6000581617
T1215A	T1216	T1216A
 GM 90443900,OPL 1208065,90449572,BOSCH 0221503001	 BOSCH,GM 93261953,F 000 ZSO201	 026 905 105,UF715
T1216B	T1216C	T1217
 F 000 ZS0 206,F 000 ZS0 207,46752948	 BOSCH,0221 504 461,LADA,2111-3705010,2111-3705010-03	 LADA,2112-3705010,2112-3705010-02
T1217A	T1217B	T1218
 LADA48.3705	 LADA72.3705	 RENAULT,7700274008,NISSAN,22448-00QAC,SAGEM 2526151A,6001543604

T1218A	T1218B	T1219
 8200 141 149,RENAULT,7700 873 701,7700 872 449	 224336134R,77080001,7700873701	 CHEVROLET,24531916,F01R00A027
T1219A	T1220	T1220A
 BOSCH,F01R00A025,0221 503 465,A11-3705110EA	 9675390980,28276583	 9671214580,28211913
T1221	T1221A	T1221B
 750GS-AQGV,190705,黄龙BJ600GS,蓝宝龙300	 钱江贝纳利,幼师金鹏公路拉力,大魔鬼 黄龙BJ300,BN302,TNT600	 CF MOTO, ODMO-178000, 短款 春风250系列
T1221C	T1221D	T1221E
 CF MOTO,0700-178000-1,长款,春风400,650系列	 33260-P200-00000,凯越机车351	 750GS-A,钱江贝纳利国四款, 黄龙300 飓风龙卷风302R

T1221F	T1221G	T1221L
 珠峰凯越机车ZF500GY-A经典版 525X	 贝纳利雀克1130K,亚马逊1130,TNT1130, 奥古斯塔MV8000,040 104 006	 钱江追700,750GS-A
T1221M	T1222C	T1222D
 299086640000,QJ900GS-8D,750GS-A 473MX(M),钱江赛921,两侧边 (长线)	 380 1 014 4B,78417001, 杜卡迪Panigale1198街霸1098机车848	 CF80-5A-7A,OPW0-GNC-00,春风800MT 800NK, 635.39.006.100,78417005,杜卡迪 KTM 790, Duke 790 890
T1235	T1235A	T1235B
 21171-0033,129700-5430	 129700-3881,30700-MBW-611,CBR-600F4	 129700-4840
T1235C	T1235D	T1235E
 IC-2068	 129700-4150,33410-35F00	 21171-1286,129700-4180


T1235F	T1235G	T1235J
 129700-3630,129700-3850,21171-1265	 5UL-82310-10-00,5UL-82310-00-00,129700-4760	 30700-KSE-003,129700-5160
T1235L	T1235N	T1235P
 21171-1272,30700-MEL-003,30700-MBW-611	 129700-5150,30700-MFL-003	 129700-3440,33410-34E00
T1235Q	T1235R	T1235W
 129700-5030,21121-0021,21121-3020	 129700-5520,21171-0751	 129700-4800,3095669
T1236	T1236B	T1300
 129700-4770,30700-KRN-670,30700-KRN-671	 129700-4580,JO458	 RENAULT,8200 051 128,8200 084 401,NISSAN,22448-00QAD

T1301	T1301A	T1400
 RENAULT,8200 360 911	 BERU,0040100325	 0 221 102004,0 221 102 036,0 221 102 078,0 221 119 002,0 221 119 009,0 221 119 012,D500,D503,D504,D508,D510,D511,D512,D514,D516,D520,DG313,F500,F501,F5012,MD003820,F0562180
T1401	T1402	T1403
 BOSCH 0221102004,UF3	 FIAT 131,FIAT 132,FIAT 147	 LUCAS DLB101
T1404	T1405	T1406
 3230427,33004522,8933004522,D5AZ-12029-A,DG314,F502,F502Z,FO400,J3230427,AMC77-87,JEEP 78-91,EAGLE 88,LINCOLN 75-84,FORD 75-91,MERCURY 75-86,FORD TRUCKSVANS 75-88	 BOSCH 0221119027	 FORD D5RY-12029A,FD476
T1407	T1408	T1410
 BOSCH 02211100001,UC14	 F&AF 12029 BA,12VOLTS MOTORCRAFT OBB	 CIZ500,22433-14816


T1501A	T1502	T1502A
 1208020.0	 55579072,55577898,55573735,1208093,1208092	 55579071,55573734,55577946,1208091,1208094
T1503	T1503A	T1504
 DELPHI,1104076,10458421,UF-266	 DELPHI,1104075,10458420,UF-265	 1104070,10457880,12580538,12587426,19428733,UF391,帶模块
T1505	T1507	T1508
 BOSCH,0 221 503 018,0001500780,0001501380,0 221 503 033,0 221 503 034	 55559955 55562588 30583218,UF-577	 5551132,9178955,UF422
T2001	T2003	T2006
 33410-95J00	 33410-94J00	 8M0029482,REV-B

T3001	T3002	T3003
 30510-K41-N01,TEC MP37,131211,V231010,1009, AB:HG0002-A-L	 30510-KZR-601, TEC MP35, 140503 V240106 121=5, 博诚: GFM-D-L	 30500-K15-901,30E3-1,SE33-K15A, 博诚: GFM-A-G
T3004	T3005	T3006
 30500-KVB-901,TEC MP40,140220,V231211 1209, 博诚: GFM-B-L	 30500-KWB-920,TEC MP41,161215,博诚: GFM-C-L	 33410-16H10-000,TEC MP31,131213,T31121, 博诚: 45H10-A-B
T3008	T3009	T3013
 1DY-H2310-00, 博诚: 2PH-A-W	 1WS-82310-00	 7715855-01,102289-10 CN,Pulse 12193L,L (左侧)
T3014	T3015	T3016
 33410-40J10-000, 博诚: HG0002-A-R,参数同T3001	 30510-K15-921, 博诚: GFM-A-L,参数同T3003	 33410-45H10-000

T3017	T3018	T3019
 54P-H2310-10	 7 715 857-01, 102289-10 CN 12189L, L(左侧)	 30510-MM8-003,IC-006
T3020	T3022	T3024
 30510-MM8-003,30701-MF5-000,30751-MR1-000,30753-MR1-000,IC-008	 30510-HM5-630	 3089239.0
T3027	T3033	T3037
 7696510-02, 102289-10 DE era 12165 Re R(右侧)	 IG 3893,080422,F15419	 27092626-0001,2CA0,LX650GS-A
T3040	T3041	T3042
 30510-KT7-023+30751-MEA-670+30700-MEA-671, IC-052/SPC-009	 30510-KT7-013 30510-KT7-023+30753-MW3-000+30700-MW3-000	 30510-KT7-013 30510-KT7-023+30753-MW3-000+30700-KK6-153

T3048	T3050	T3054
 48H-B(H) A0605-00015	 125TB-HJ A0605-00038	 GFM(Ⅱ)-A-G A0605-00035
T3055	T3060	T3068
 HG0002-A-G A0605-00034	 JP351207, DK111064,V.CODEF:100172 KTM390	 GFM(Ⅱ)-A-L, 白料
T3069	T3070	T3071
 GFM(Ⅱ)-B-L, 白料	 GFM(Ⅱ)-D-L, 白料	 GFM(Ⅱ)-C-G, 白料
T3072	T3075	T3077
 125TB (Φ6.2) ,A0605-00008 黑色和绿色都是6.3mm,外壳孔Φ6.2	 33410-33G31	 G1060370,TVS200-2

T3079  ZF400GS-A,332600-T300-00001,332600-T300-00000, 凯越机车	T3080  230100-EFR05-00000, 张雪机车	T3097  30510K1BT01,本田佛沙350
T3098  AT-5111GGS,332600-P200-00000	T3099  336200-T510-00002,凯越机车	T3100  332600-W400-00000,凯越机车
T3101  2560231019,13991	T3102  900011523,C12H	T3103  3C00-50000-00
T3104  凯越机车650RR,332600-X300-00000	T3105  900014045,C25DI	T3106  332600-W400-00001

T3108	T3115	T3116
 202200-P20A-0003, 莫里尼	 96200U320000	 双缸250-1 A0605-00045
T3117	T4001	T4006
 380.4.025.1A, 77380008 线长75mm, 2019-2022 杜卡迪1260cc	 A-02 双缸航模机点火线圈, 四缸航模机点火线圈	 单缸航模机点火线圈, 转子发动机点火线圈
T4009	T4010	T4011
 8015主体, 450线长 9021B火花帽 (湖南懿鹏)	 8015主体, A-----360mm, a、B、b----340mm 9021B火花帽 (全志机电)	 8022主体,450线长,9021B火花帽
T4012	T4013	T4014
 8022主体, 350mm线长, 9017火花帽 NGK CR9E1X (陕西众科)	 8013主体, 350mm线长, 9017火花帽 NGK CR9E1X (陕西众科)	 8015主体, 180mm线长, 9021B火花帽

T4015	T5003	T5004
 8015主体,340线长,匹配CM-9火花塞(福爱电子)	 99-2916,99-2911,KC179	 100-2948,99-2912,KC179A
T5005	T5006	T5007
 14 584 04-S,KC135K-2A	 30500-ZE1-033,KC168-2	 491760,493237,KC1104J-4
T5008	T5009	T5010
 35135,35135A,KC1130A	 34443,34443A,KC1130	 30500-ZL8-004,KC153B
T5011	T5012	T5013
 20 584 03-S,KC1176	 1258404S,KC1186A	 0000 400 1300,KC165F-1

T8001  AT-5111GGS,332600-P200-00000	T8002  ZF400GS-A,332600-T300-00001,332600-T300-00000, 凯越机车	T8003  332600-R110-00000,凯越525X
T8004  150100-EBS01-000, 凯越800	T8007  336200-T510-00002 凯越机车	T8010  332600-W400-00000 凯越机车
T8012  2560231019,13991	T8013  福爱电子,DFAA01100015	T8015  900011523,C12H
T8016  3C00-50000-00	T8017  凯越650RR 332600-X300-00000	T8022  900014045,C25DI

T8027	T8028	T8036
 230100-EFR05-00000,张雪机车	 332600-W400-00001	 304000-0148,1200CC,(重庆摩疆)
T8038	T8050	
 202200-P20A-0003, 莫里尼	 3051A-J3AN-9000,金浪科技	



江苏云意电气股份有限公司
JIANGSU YUNYI ELECTRIC CO.,LTD

地址 (ADD) : 江苏省徐州市铜山区黄山路26号
#26, HUANGSHAN RD, TONGSHAN AREA, XUZHOU,
JIANGSU, CHINA, 221116

电话 (TEL) : 0086-516-83505462
0086-516-83538150

传真 (FAX) : 0086-516-83507801

E-mail: yunyixz@yunyi-china.cn
Web: www.yunyi-china.net

YY-V1.0-20260908

Tip: All the manufacturers names, product numbers and pictures referred are used for reference only.
提示:所有涉及到的厂家的名称、型号及图片, 仅做参考, 规格请以实物为准!